347 Flushing Avenue, Brooklyn

Interior Photographs Key (Sub-Cellar Level)



Photographs Taken By Patrick O'Shea on May 28, 2024

Urban Cartographics



1. View of the sub-cellar level garage facing east.



2. View of the ramp descending into the sub-cellar level garage facing west.



3. View of the sub-cellar level garage facing northwest.



4. View of the sub-cellar level garage facing south.

347 Flushing Avenue, Brooklyn

Interior Photographs Key (Cellar Level)



Photographs Taken By Patrick O'Shea on May 28, 2024



5. View of the cellar floor garage facing east.



6. View of the cellar floor facing southwest.



7. View of the storage facility in the cellar floor facing east.



8. View of the storage facility in the cellar floor facing east.

347 Flushing Avenue, Brooklyn

Interior Photographs Key (Ground Floor)



Photographs Taken By Patrick O'Shea on May 28, 2024



9. View of the ground floor entry facing east.



10. View of the ground floor entry facing west.

347 Flushing Avenue, Brooklyn

Interior Photographs Key (Second Floor)



Photographs Taken By Patrick O'Shea on May 28, 2024



11. View of the second floor luxury clothing shop facing west.



12. View of the second floor facing east.



13. View of the second floor luxury clothing shop facing east.



14. View of the second floor escalators facing west.

347 Flushing Avenue, Brooklyn

Interior Photographs Key (Third Floor)



Photographs Taken By Patrick O'Shea on May 28, 2024



15. View of the third floor facing east.



16. View of the third floor accessory store facing south.



17. View of the third floor clothing store facing east.



18. View of the third floor jewelry store facing west.

347 Flushing Avenue, Brooklyn

Interior Photographs Key (Fourth Floor)



Photographs Taken By Patrick O'Shea on May 28, 2024



19. View of the fourth floor nurses station facing northeast.



20. View of the fourth floor hallway facing east.



21. View of the fourth floor staff break room facing northeast.



22. View of the fourth floor healthcare facility offices southwest.

347 Flushing Avenue, Brooklyn

Interior Photographs Key (Sixth Floor)



Photographs Taken By Patrick O'Shea on May 28, 2024



23. View of the sixth floor hallway facing east



24. View of the sixth floor hallway facing west.



25. View of the sixth floor offices facing southwest.



26. View of the sixth floor office conference room facing northwest.

347 Flushing Avenue, Brooklyn

Interior Photographs Key (Seventh Floor)



Photographs Taken By Patrick O'Shea on May 28, 2024



27. View of the seventh floor hallway facing west.



28. View of the seventh floor hallway facing east.



29. View of the seventh floor office breakroom facing northwest.



30. View of the seventh floor offices facing southeast.